

PROBLEM.

RV crash closes I-70

A woman was taken by CareFlight to Miami Valley Hospital and her husband taken by ambulance to the hospital after their recreational vehicle overturned on Interstate 70, near the Arlington Road exit, on Sunday evening. The accident closed both west bound lanes and one east bound lane for several hours.

The couple was traveling east on I-70 around 5:45 p.m. when the RV's left front tire blew, causing the vehicle to go into the medium and overturn, according to the Ohio State Patrol.

SOLVED.

Every wheel is made with this low area or "well"



An exposed well causes vehicle instability when a tire goes flat

Tyron[®] is installed over the "well" to lock your tire to the wheel



A flat tire now forms a cushion of rubber between wheel and road

TYRON[®]

BLOWOUT PROTECTION SO EFFECTIVE IT'S PATENTED

ASK YOUR RV RETAILER FOR FULL DETAILS